



## **16” Subsea Oil Pipeline Riser Repair, Platform Elly**

**Beta Offshore Production Complex, Long Beach, California**  
**Client: Beta Offshore**

During an internal inspection of Beta Offshore’s 16” San Pedro Bay Pipeline (SPBPL), an area of 50% wall loss due to external corrosion was identified in the surf zone on Platform Elly.

DPSI worked closely with the following agencies to design an approved repair solution:

- Bureau of Ocean Energy Management, Regulation and Enforcement (BOEMRE)
- California State Lands Commission
- US Department of Transportation (DOT) Office of Pipeline Safety

Work was accomplished during a period of adverse weather conditions and high seas in order to allow the pipeline to remain in service. This project was the final step necessary to allow a right-of-way agreement to be finalized with the California State Lands Commission.